

25 October 1965

MEMORANDUM FOR THE RECORD

SUBJECT: Trip Report

1. On October 20, I visited [REDACTED] for the main purpose of inspecting the Panoramic Stereo Viewer. [REDACTED] Project Engineer, was present during the inspection period.

STATINTL
STATINTL

2. The viewer has been greatly improved since the last complete inspection. Some of the most important changes are:

- a. Glass drums have been substituted for the plastic ones originally on the instrument.
- b. Hot spots in the illumination system have been eliminated.
- c. The manual drive problems have been solved. It is now possible to move the film on the glass drum without slippage.
- d. The noisy gears in the drive system have been replaced with fiber gears.
- e. The head rest over the eyepieces has been modified so that it can be adjusted to various positions.
- f. An adjustable mask has been added to the auxiliary light source to shield the portion of the fluorescent tube extending beyond the edge of the film when widths narrower than $9\frac{1}{2}$ inches are used.

3. Delivery of the instrument will be made in approximately two weeks. A few minor items will need to be checked before shipment. These include the following:

- a. Adjustment of several loose knobs.
- b. Correcting an annoying noise in the drive for the left glass drum.
- c. Repositioning the reticle in one of the eyepieces.

DECLASS REVIEW by NIMA/DOD

d. Adding a film loading diagram in a convenient location.

Arrangements are being made to have the viewer delivered directly to
[REDACTED] instead of the [REDACTED] warehouse.

STATINTL

STATINTL